

Light measurement report



Laboratory and Equipment

Test lab	n/a
Spectrometer Manufacturer and Model	n/a, n/a – n/a
Measurement date	7/14/2026

Measurement Conditions

Tested c-planes	12
Tested gamma angles	181 – 1.00°
Input Power	2.892 W


Tested Light Source

Luminaire	2022/10/24 11:12:55
Basic Luminous Shape	PANEL
Item No.	
Manufacturer	Moon On Noon


Main Light Measurement Results

Output – Total Lumen (Up% / Down%)	58.75 lm – 0.0005% / 100%
Efficiency	20.31 lm/W
Peak Intensity	362.8 cd
Correlated Color Temperature, CCT	3000 K
Color Rendering Index	CRI 85.0

Polar light distribution diagram




Beam details




Luminaire budgetary diagram


LAMPS (number of lamps)




Iso-intensity Diagram (Iso-candela)



Iso-illuminance Diagram (Iso-lux)




Linear intensity distribution diagram



IESNA TM-15-07 Luminaire Classification System For Outdoor Luminaires

BUG rating B0 U0 G0



Forward Light

Low (0-30°)	33.1 lm	56.4%
Medium (30-60°)	0.9 lm	1.6%
High (60-80°)	0.2 lm	0.4%
Very High (80-90°)	0.1 lm	0.1%

Back Light

Low (0-30°)	23.1 lm	39.3%
Medium (30-60°)	1.0 lm	1.6%
High (60-80°)	0.3 lm	0.4%
Very High (80-90°)	0.1 lm	0.1%

Uplight

Low (90-100°)	0.0 lm	0.00%
High (100-180°)	0.0 lm	0.0%

Total

Sum	58.7 lm	100,0%
-----	---------	--------