

Light measurement report



Laboratory and Equipment

Test lab	n/a
Spectrometer Manufacturer and Model	n/a, n/a – n/a
Measurement date	7/14/2026

Measurement Conditions

Tested c-planes	8
Tested gamma angles	181 – 1.00°
Input Power	59.83 W


Tested Light Source

Luminaire	2021/4/5 11:21:03
Basic Luminous Shape	PANEL
Item No.	
Manufacturer	Moon On Noon


Main Light Measurement Results

Output – Total Lumen (Up% / Down%)	3472 lm – 0.0014% / 100%
Efficiency	58.03 lm/W
Peak Intensity	7485 cd
Correlated Color Temperature, CCT	3000 K
Color Rendering Index	CRI 85.0

Polar light distribution diagram




Beam details




Luminaire budgetary diagram


LAMPS (number of lamps)




Iso-intensity Diagram (Iso-candela)



Iso-illuminance Diagram (Iso-lux)




Linear intensity distribution diagram



IESNA TM-15-07 Luminaire Classification System For Outdoor Luminaires

BUG rating B3 U0 G0



Forward Light

Low (0-30°)	1346.8 lm	38.8%
Medium (30-60°)	372.4 lm	10.7%
High (60-80°)	42.6 lm	1.2%
Very High (80-90°)	7.5 lm	0.2%

Back Light

Low (0-30°)	1305.9 lm	37.6%
Medium (30-60°)	348.6 lm	10.0%
High (60-80°)	40.5 lm	1.2%
Very High (80-90°)	7.3 lm	0.2%

Uplight

Low (90-100°)	0.0 lm	0.00%
High (100-180°)	0.0 lm	0.0%

Total

Sum	3471.8 lm	100,0%
-----	-----------	--------